

SIEMENS

Ingenuity for life

Industry Online Support

Home

Replace FB LGF_TimerSwitch

STEP 7 (TIA Portal)

<https://support.industry.siemens.com/cs/ww/en/view/109479728>

Siemens
Industry
Online
Support



This entry is from the Siemens Industry Online Support. The general terms of use (http://www.siemens.com/terms_of_use) apply.

Security information

Siemens provides products and solutions with industrial security functions that support the secure operation of plants, systems, machines and networks. In order to protect plants, systems, machines and networks against cyber threats, it is necessary to implement – and continuously maintain – a holistic, state-of-the-art industrial security concept. Siemens' products and solutions only form one element of such a concept.

Customer is responsible to prevent unauthorized access to its plants, systems, machines and networks. Systems, machines and components should only be connected to the enterprise network or the internet if and to the extent necessary and with appropriate security measures (e.g. use of firewalls and network segmentation) in place.

Additionally, Siemens' guidance on appropriate security measures should be taken into account. For more information about industrial security, please visit <http://www.siemens.com/industrialsecurity>.

Siemens' products and solutions undergo continuous development to make them more secure. Siemens strongly recommends to apply product updates as soon as available and to always use the latest product versions. Use of product versions that are no longer supported, and failure to apply latest updates may increase customer's exposure to cyber threats.

To stay informed about product updates, subscribe to the Siemens Industrial Security RSS Feed under <http://www.siemens.com/industrialsecurity>.

Table of content

1	Introduction	3
2	Procedure	3

1 Introduction


The FB LGF_TimerSwitch lost the connection to the type in the library LGF V4.0.0 for TIA portal V14 SP1 and the library LGF V4.0.1 for TIA portal V15. Therefore an update of an older version of the FB was not possible. With the libraries V 4.0.2 for TIA portal V14 SP1 and TIA portal V15 an update of the FB for older library versions than V4.0.0 is possible again.

If you use the FB LGF_TimerSwitch out of the library V 4.0.0 for TIA portal V14 SP1 or the library V 4.0.1 for TIA portal V15 in your project, you must replace this with the new version to be able to update the FB in the future.


2 Procedure

To replace the FB LGF_TimerSwitch in your project with the new version, proceed as follows:

1. Delete the FB LGF_TimerSwitch in the project library and in your project.
2. Confirm the dialog with "Yes".



3. Activate the check box "Apply to all elements" and confirm the dialog with "OK".



4. Insert the FB LGF_TimerSwitch out of the library LGF V4.0.2 by Drag & Drop into the original location in the project navigation.